





RQ-5688
 Rec'd 1/29/2016
 C16-0179

Flex Fuel Ford Interceptor Police Rated OPD

Fleet Management Division Vehicle Requisition FY 2015/2016

| | |
|---|---|
| Vehicle Class: | BAPL , BAPP, BAPS and BAPH - 72 MONTHS |
| Description: | Flex-Fuel Ford Interceptor Police Rated Utility Vehicle, 3.7L TI-VCT V6 Engine, 6 Speed Auto Transmission, Cloth Front Buckets/ Rear Vinyl W/Black Interior, Equipment Package, Front License Bracket, Back-up Camera displayed in the 4" center stack, Front Headlamp / Police Interceptor Housing Only- Pre-drilled hole, Tail Lamp / Police Interceptor Housing Only- Pre-drilled hole, Remote Keyless Entry Key Fob, Hidden Door-Lock Plunger w/Rear-door handles inoperable, Rear window switches inoperative, Courtesy lamp disabled, Dome lamp - red/white in Cargo Area, Reverse sensing, Anti Theft, Yellow CITY Tag, (2) Additional Key Fobs - Programmed, (2) Additional Key - Cut & Programmed, 6 year/125,000 miles Premium Care Warranty with Zero Deductible, 6 year/125,000 mile Maintenance Plan - 25 service visits at 5000 mile intervals, zero deductible. Piggy Back the State of Florida Contract No.:25100000-16-1, Line Item 18 with the attached quote. |
| Quantity: | 48 |
| Estimated Cost: | \$32,661.75 Each, \$1,567,764.00 Total |
| Cost Center: | FLT0005_C |
| Requisition Number: | |
| Purchase Order Number: | |
| Buyers Notes: | Flex-Fuel Ford Interceptor Police Rated Utility Vehicle, 3.7L TI-VCT V6 Engine, 6 Speed Auto Transmission, Cloth Front Buckets/ Rear Vinyl W/Black Interior, Equipment Package, Front License Bracket, Back-up Camera displayed in the 4" center stack, Front Headlamp / Police Interceptor Housing Only- Pre-drilled hole, Tail Lamp / Police Interceptor Housing Only- Pre-drilled hole, Remote Keyless Entry Key Fob, Hidden Door-Lock Plunger w/Rear-door handles inoperable, Rear window switches inoperative, Courtesy lamp disabled, Dome lamp - red/white in Cargo Area, Reverse sensing, Anti Theft, Yellow CITY Tag, (2) Additional Key Fobs - Programmed, (2) Additional Key - Cut & Programmed, 6 year/125,000 miles Premium Care Warranty with Zero Deductible, 6 year/125,000 mile Maintenance Plan - 25 service visits at 5000 mile intervals, zero deductible. Piggy Back the State of Florida Contract No.:25100000-16-1, Line Item 18 with the attached quote. Delivered with the Keys and Invoice to 1010 S. Westmoreland Drive, Orlando, Fl. 32805. Questions contact Daryl Greenlee 407-246-3065. Vehicles will not be accepted by City of Orlando until all the stipulations have been fulfilled. |
| Police Chief |  1-28-16 |
| Fleet & Facilities Division Manager |  1-22-16 |
| Fleet & Facilities Assistant Division Manager |  1-22-16 |
| Fleet Manager |  1-22-16 |

Flex Fuel Ford Interceptor Police Rated OPD

| Unit Count | New/ Replace | Program | Class | Old Vehicle Number | New Vehicle Number | Actual Cost | Date Received | Received By |
|------------|--------------|---------|-------------|--------------------|--------------------|-------------|---------------|-------------|
| 1 | Replace | 675 | BAPS | 6616 | | | | |
| 4 | Replace | 678 | BAPH | 6810 | | | | |
| 2 | Replace | 678 | BAPL | 6823 | | | | |
| 3 | Replace | 691 | BAPL | 7132 | | | | |
| 5 | Replace | 678 | BAPL | 7166 | | | | |
| 6 | Replace | 691 | BAPL | 7440 | | | | |
| 7 | Replace | 693 | BAPL | 7457 | | | | |
| 8 | Replace | 678 | BAPL | 7466 | | | | |
| 9 | Replace | 691 | BAPL | 7498 | | | | |
| 10 | Replace | 691 | BAPL | 7501 | | | | |
| 11 | Replace | 692 | BAPP | 7724 | | | | |
| 12 | Replace | 691 | BAPL | 7727 | | | | |
| 13 | Replace | 691 | BAPL | 7774 | | | | |
| 14 | Replace | 691 | BAPL | 7780 | | | | |
| 15 | Replace | 691 | BAPL | 8042 | | | | |
| 16 | Replace | 691 | BAPL | 8044 | | | | |
| 17 | Replace | 692 | BAPL | 8046 | | | | |
| 18 | Replace | 692 | BAPL | 8047 | | | | |
| 19 | Replace | 692 | BAPL | 8051 | | | | |
| 20 | Replace | 691 | BAPL | 8052 | | | | |
| 21 | Replace | 691 | BAPL | 8054 | | | | |
| 22 | Replace | 693 | BAPL | 8057 | | | | |
| 23 | Replace | 691 | BAPL | 8059 | | | | |
| 24 | Replace | 693 | BAPL | 8061 | | | | |
| 25 | Replace | 693 | BAPL | 8062 | | | | |
| 26 | Replace | 692 | BAPL | 8063 | | | | |
| 27 | Replace | 692 | BAPL | 8064 | | | | |
| 28 | Replace | 691 | BAPL | 8070 | | | | |
| 29 | Replace | 693 | BAPL | 8072 | | | | |
| 30 | Replace | 692 | BAPL | 8079 | | | | |
| 31 | Replace | 691 | BAPL | 8082 | | | | |
| 32 | Replace | 692 | BAPL | 8083 | | | | |
| 33 | Replace | 691 | BAPL | 8086 | | | | |
| 34 | Replace | 691 | BAPL | 8091 | | | | |
| 35 | Replace | 691 | BAPL | 8092 | | | | |
| 36 | Replace | 691 | BAPL | 8095 | | | | |
| 37 | Replace | 691 | BAPL | 8096 | | | | |
| 38 | Replace | 691 | BAPL | 8097 | | | | |
| 39 | Replace | 691 | BAPL | 8100 | | | | |

Flex Fuel Ford Interceptor Police Rated OPD

| | | | | | | | | |
|----|---------|-----|-------------|------|--|--|--|--|
| 40 | Replace | 691 | BAPL | 8106 | | | | |
| 41 | Replace | 692 | BAPL | 8109 | | | | |
| 42 | Replace | 691 | BAPH | 8126 | | | | |
| 43 | Replace | 691 | BAPL | 8167 | | | | |
| 44 | Replace | 675 | BAPL | 8277 | | | | |
| 45 | Replace | 691 | BAPL | 8452 | | | | |
| 46 | Replace | 691 | BAPL | 8748 | | | | |
| 47 | Replace | 692 | BAPL | 8753 | | | | |
| 48 | Replace | 691 | BAPL | 9320 | | | | |

CONDITIONS

In addition to equipment specified, vehicle shall be equipped with all standard equipment as specified by the manufacturer for this model and shall comply with all EPA Emission Standards and all Motor Vehicle Safety Standards as established by the U.S. Department of Transportation regarding the manufacture of motor vehicles.

The vendor shall be responsible for delivering the vehicle properly serviced, clean and in first class operating condition. Pre-delivery service, at a minimum, shall include the following:

- a) Complete lubrication.
- b) Check all fluid levels to assure proper fill.
- c) Adjustment of engine to proper operating condition.
- d) Inflate tires to proper pressure.
- e) Check to assure proper operation of all accessories, gauges, lights, and mechanical features.
- f) Focusing of headlights.

DO NOT remove window price sticker or supplied line sheet from the vehicle. Put in the glove box.